

PRODUCT CHANGE NOTIFICATION

Reference: **EP_1491264**

Issue: **0**

Date of Publication: **20th of January 2026**

AFFECTED PRODUCT

LIE Part Number: **GP5 standard series.**


LIE Designation: **Non-latching relay, 2PDT / 2A.**

DESCRIPTION OF THE EVOLUTION

Replacement of the moving blades reference 005B7028 by the moving blades reference 68 7502 18 used on another relay series.



Current version - 005B7028



alternative version - 68 7502 18

EVOLUTION TYPE

Secondary Minor Major

IMPACT ON / IDENTIFICATION OF THE EVOLUTION

Part number <input type="checkbox"/>	Amdt <input type="checkbox"/>	Serial number <input type="checkbox"/>	Date code <input checked="" type="checkbox"/>	Other <input checked="" type="checkbox"/>
Before:	Before:	From S/N:	From DC: 26/07	
After:	After:			

RATIONAL

This change follows the receipt of several batches of non-compliant moving blades which have generated sorting operations and a high scrap rate. The manufacturing process of the replacement moving blades is more efficient, this will maintain the level of performance and improve the production time series. This change will be done on all standard GP5 relays series.

JUSTIFICATION

According to the fact that these moving blades are mounted in another relay family with a similar dimensions and environmental constraints and that validation tests have been performed, Leach International concluded that this modification has no impact on the Qualification test results of the GP5 standard and customers specifics relays series (refer to Test Report 1400809 issue 0).

We remain committed to provide on time quality products and confident this action will better serve you.

For any question relating to this PCN, please contact your vendor or ask your question through LEACH website.