

**PRODUCT CHANGE NOTIFICATION**

Reference: **EP\_1467435**

Issue: **0**

Date of Publication: **06<sup>th</sup> of February 2025**

**AFFECTED PRODUCT**

**LIE Part Number:** **F/FD37X, F/FD47X, F/FD67X relays series.**

**LIE Designation:** **Electromechanical relays.**

**DESCRIPTION OF THE EVOLUTION**

**Addition of a second manufacturing site for F/FD37X, F/FD47X, F/FD67X relays series. Relays are manufactured in France or India.**

**EVOLUTION TYPE**

Secondary                       Minor                       Major

**IMPACT ON/ IDENTIFICATION OF THE EVOLUTION**

<b>Part number</b> <input type="checkbox"/>	<b>Amdt</b> <input type="checkbox"/>	<b>Serial number</b> <input type="checkbox"/>	<b>Date code</b> <input type="checkbox"/>	<b>Other</b> <input checked="" type="checkbox"/>
Before:	Before:	From S/N:	From DC:	Refer to note 1
After:	After:			

**Note1: Relays manufactured in India are identified with M character at the end of the date code.**

**RATIONAL**

**In Order to support our customers' growth, LEACH has developed several manufacturing capabilities (MIL-STD-790, ISO 9001, and AS 9100 certified). This new manufacturing site will help to secure OTD and customer service (reduction of risk). This manufacturing site allow to increase the production capacity of the relays listed above.**

**JUSTIFICATION**

**All qualification tests have been carried out successfully, and all requirements fulfilled. All evidence can be consulted on LEACH site.**

We remain committed to provide on time quality products and confident this action will better serve you.

For any question relating to this PCN, please contact you vendor or ask your question though LEACH website.