

PRODUCT CHANGE NOTIFICATION

Reference: **EP_1482467**

Issue: **0**

Date of Publication: **25th of June 2025**

AFFECTED PRODUCT

LIE Part Number: **D, E and GP5 relays series.**

LIE Designation: **Latching and non-latching relay, 2 PDT / 1 or 2A.**

DESCRIPTION OF THE EVOLUTION

Use of a coil housing with a PEEK material instead of NYLON PA 6.6 LS raw material.

EVOLUTION TYPE

☐ Secondary

☒ Minor

☐ Major

IMPACT ON / IDENTIFICATION OF THE EVOLUTION

Part number <input type="checkbox"/>	Amdt <input type="checkbox"/>	Serial number <input type="checkbox"/>	Date code <input checked="" type="checkbox"/>	Other <input type="checkbox"/>
Before:	Before:	From S/N:	From DC: 25/20	
After:	After:			

RATIONAL

Due to the obsolescence of the PA 6.6 NYLON raw material, implementation of coil housing with a PEEK (KETRON 1000) material.

JUSTIFICATION

**Verification tests are performed to demonstrate the non-regression of the components.
All evidence is consultable on LEACH site in the test report reference RT_1456926 issue 2.**

We remain committed to provide on time quality products and confident this action will better serve you.

For any question relating to this PCN, please contact you vendor or ask your question though LEACH website.