

PRODUCT CHANGE NOTIFICATION

Reference: **EP_1504870**

Issue: **0**

Date of Publication: **04th of MARCH 2026**

AFFECTED PRODUCT

LIE Part Number: S2XX-XXXX

LIE Designation: SXXX RELAYS SOCKET SERIES

DESCRIPTION OF THE EVOLUTION

Replacement of the self-locking nuts reference 31 520 00M with the self-locking nuts reference 31 520 12.

EVOLUTION TYPE

- Secondary Minor Major

IMPACT ON / IDENTIFICATION OF THE EVOLUTION

Part number <input type="checkbox"/>	Amdt <input type="checkbox"/>	Serial number <input type="checkbox"/>	Date code <input checked="" type="checkbox"/>	Other <input type="checkbox"/>
Before:	Before:	From S/N:	From DC: 14/27	
After:	After:			

RATIONAL

Both self-locking nuts have the same dimensions, the same raw material. The difference is only related to the surface treatment.

JUSTIFICATION

According to the fact that both self-locking nuts have the same dimensions, the same raw material and that the differences are only related to the surface treatment which have been verified by tests, Leach International concluded that this modification has no impact on the Qualification test results of the S2XX-XXX relays sockets series (refer to Test Report 1326849 issue 0).

We remain committed to provide on time quality products and confident this action will better serve you.

For any question relating to this PCN, please contact you vendor or ask your question though LEACH website.