

PRODUCT CHANGE NOTIFICATION

Reference: **EP_1505661**

Issue: **0**

Date of Publication: **4th of March 2026**

AFFECTED PRODUCT

LIE Part Number: **M212 relays series**

LIE Designation: **Latching relay, 2 PDT / 5A**

DESCRIPTION OF THE EVOLUTION

Use of a coil housing with a PEEK material instead of NYLON PA 6.6 LS raw material.

EVOLUTION TYPE

- Secondary Minor Major

IMPACT ON / IDENTIFICATION OF THE EVOLUTION

| Part number <input type="checkbox"/> | Amdt <input type="checkbox"/> | Serial number <input type="checkbox"/> | Date code <input checked="" type="checkbox"/> | Other <input type="checkbox"/> |
|---|--------------------------------------|---|--|---------------------------------------|
| Before: | Before: | From S/N: | From DC: | |
| After: | After: | | 26-11 | |

RATIONAL

Due to the obsolescence of the PA 6.6 NYLON raw material, implementation of coil housing with a PEEK (KETRON 1000) material.

JUSTIFICATION

Verification tests are performed to demonstrate the non-regression of the components. All evidence is consultable on LEACH site in the test report reference RT_1468267 issue 0

We remain committed to provide on time quality products and confident this action will better serve you.

For any question relating to this PCN, please contact you vendor or ask your question though LEACH website.