

**PRODUCT CHANGE NOTIFICATION**

Reference: **EP\_1508325**

Issue: **0**

Date of Publication: **04<sup>th</sup> of MARCH 2026**

**AFFECTED PRODUCT**

**LIE Part Number:** **F600-XXX and FE2024.**

**LIE Designation:** **Relays and time delay relay.**

**DESCRIPTION OF THE EVOLUTION**

**The brackets reference 68 0033 00 of the can used on F600 relay series and FE2024 time delay relay is replaced with the brackets reference 68 0033 10.**

**EVOLUTION TYPE**

Secondary                       Minor                       Major

**IMPACT ON / IDENTIFICATION OF THE EVOLUTION**

<b>Part number</b> <input type="checkbox"/>	<b>Amdt</b> <input type="checkbox"/>	<b>Serial number</b> <input type="checkbox"/>	<b>Date code</b> <input checked="" type="checkbox"/>	<b>Other</b> <input type="checkbox"/>
Before:	Before:	From S/N:	From DC: <b>10/26</b>	
After:	After:			

**RATIONAL**

**This modification is due to a change of supplier and new manufacturing tooling.**

**JUSTIFICATION**

**This modification is introduced to ensure configuration harmonization across the F600 relay series and FE2024 time delay relay without impacting fit, form, and function.  
The form change (The bracket edges have been rounded) to reduce sharp edge.**

We remain committed to provide on time quality products and confident this action will better serve you.

For any question relating to this PCN, please contact you vendor or ask your question though LEACH website.